

INFORMATIONAL MEMORANDUM

TO: Transportation & Infrastructure Services Committee

FROM: Hari Ponnekanti, Public Works Director/City Engineer

BY: Griffin Lerner, Public Works Analyst

CC: Mayor Allan Ekberg

DATE: November 3, 2023

SUBJECT: <u>35th Ave South</u> Street Vacation Amendment Resolution Setting Public Hearing

<u>ISSUE</u>

Approve a Resolution and set a Public Hearing date for December 4, 2023, to amend Ordinance 1978 vacating 35th Ave South.

BACKGROUND

In October of 2001, City Council adopted Ordinance 1978, vacating a portion of 35th Ave South adjacent to Sabey Data Center. This vacation included a condition that the vacated portion of 35th Ave South remain open to pedestrian traffic. In October of 2005, Council subsequently adopted Ordinance 2101, vacating a portion of 124th Street. As a result, the vacated portion of 35th Ave South does not connect to any other facility.

DISCUSSION

In 2021, Sabey applied for and obtained a construction permit to physically secure the perimeter of the Intergate East Campus in an effort to curb crime and theft from vehicles parked on the campus. Because this fencing impedes pedestrian access, the Sabey Corporation is requesting that the City remove the pedestrian easement from Ordinance 1978 in light of the crime concerns as well as prior vacations disconnecting the adjacent road from useable pedestrian access. To remove these easements, the City Council must approve a Resolution setting a Public Hearing date of December 4, 2023, to consider the proposed amendment.

FINANCIAL IMPACT

None.

RECOMMENDATION

Council is being asked to consider this item at the November 13, 2023 Committee of the Whole meeting and set a subsequent Public Hearing date of December 4, 2023.

ATTACHMENTS: Draft Resolution setting Public Hearing for 12/4/23

Vicinity Map Ordinance 1978 Sabey Letter to the City Incident Reports DRAFT

A RESOLUTION OF THE CITY COUNCIL OF THE CITY OF TUKWILA, WASHINGTON, FIXING THE TIME FOR A PUBLIC HEARING FOR VACATION OF RIGHT-OF-WAY WITHIN THE CITY OF TUKWILA DEDICATED FOR STREET PURPOSES, GENERALLY DESCRIBED AS 35th AVE SOUTH, LYING BETWEEN THE SOUTHERNLY MARGIN OF SOUTH 124TH STREET AND NORTHERNLY OF THE NORTH LINE OF LOT 4 OF PLAT OF DONALDSON ADDITION.

WHEREAS, the Sabey Corporation has petitioned the City to vacate 35th Ave South, lying between the southernly margin of South 124th Street and northernly of the North line of Lot 4 of Plat of Donaldson Addition; and

WHEREAS, pursuant to RCW 35.79.010, a public hearing on a street vacation must be set by resolution;

NOW, THEREFORE, THE CITY COUNCIL OF THE CITY OF TUKWILA, WASHINGTON, HEREBY RESOLVES AS FOLLOWS:

Section 1. A public hearing regarding the requested vacation of 35th Ave South, lying between the southernly margin of South 124th Street and northernly of the North line of Lot 4 of Plat of Donaldson Addition, more particularly described on the attached map, shall be held before the Tukwila City Council in the City Council Chambers at Tukwila City Hall, 6200 Southcenter Boulevard, Tukwila, Washington, on December 4, 2023 at 7:00 P.M., which is not less than 20, nor more than 60 days from the date of passage of this resolution, at which time all persons interested in said right-of-way vacation are invited to appear and be heard.

Section 2. The City Clerk is directed to post written notice of pendency of the public hearing in three public places in the City of Tukwila and in one additional conspicuous place on the right-of-way sought to be vacated at least 20 days prior to the date set for the public hearing.

PASSED BY THE CITY COUNCIL OF THE CITY OF TUKWILA, WASHINGTON, at a Special Meeting thereof this ______ day of ______, 2023.

ATTEST/AUTHENTICATED:

Christy O'Flaherty, MMC City Clerk

APPROVED AS TO FORM BY:

Cynthia Delostrinos Johnson Council President

Resolution Number:

Filed with the City Clerk:_____ Passed by the City Council:_____

Office of the City Attorney

Attachment: Map



S 126th St

Tukwila International Blvd

allBlvd

SEA1

King County Metro Interim Base


FINAIS

Nays

Beauty salon

S 126th St

S 126th St





SABEY ARCHITECTURE seattle, washington 206.281.8700 sabey.com



SITE PLAN

PROJECT OVERVIEW

A0.133

All drawings and written material appearing herein constitt and unpublished work of the Sabey Corporation and the be duplicated, used or disclosed without the written of Sabey Composition

FILE: IGE - SECURED PERMETER 7-23-21

PROJECT NO:


PROGRESS DATE: DRAWN BY: CHECKED BY: APPROVED BY: 7/23/21 TLS

ISSUE:

MARK DATE DESCRIPTION

3355 S 120TH PL TUKWILA, WA 98168

CAPITAL IMPROVEMENT: INTERGATE.EAST SECURED PERIMETER





City of Tukwila

Washington

Ordinance No.

AN ORDINANCE OF THE CITY COUNCIL OF THE CITY OF TUKWILA, WASHINGTON, VACATING THE NORTHERLY 623.85 FEET OF 35TH AVENUE SOUTH FROM SOUTH 126TH STREET, LOCATED IN THE CITY OF TUKWILA; AMENDING THE OFFICIAL STREET MAP OF THE CITY; PROVIDING FOR SEVERABILITY; AND ESTABLISHING AN EFFECTIVE DATE.

WHEREAS, the City Council of the City of Tukwila conducted public hearings on October 16 and November 6, 2000, for the purpose of considering the vacation of certain property located in the City of Tukwila as described above, and

WHEREAS, TMC Chapter 11 60 identifies street vacation procedures including a public hearing by resolution, Department of Community Development and Public Works review and comment, and forwarding all relevant information to City Council, all of which have been done, and

WHEREAS, after the conclusion of the public hearing the City Council found that the property should be vacated subject to certain conditions, and

WHEREAS, the condition specified in the Council Motion of November 6, 2000, regarding easements to Seattle City Light, Val Vue Sewer District, King County Water District No 125 and Puget Sound Energy has been fulfilled, and

WHEREAS, an appraisal and compensation of \$85,780 have been provided to the City in accordance with TMC Chapter 11 60, and

WHEREAS, a 50-foot easement with 35 feet of pavement (matching the current width) shall be granted to the owner of property identified as Assessors Parcels 206360-0005, 0020, 0025, 0030, 0035, and 0036 for the purposes of ingress and egress and utilities if the parcels of the property redevelop and the land use changes from residential to a permitted use within the Zoning Code, and such easement shall run with the land and shall be binding on all parties having or acquiring any right, title or interest in the land described herein, or any part thereof, as long as the present facility or any business replacing it shall need the use of these parcels for the purposes described above; and

WHEREAS, provision shall be made for emergency access to the southerly portion of the vacated area from South 126th Street and 35th Avenue South; and

WHEREAS, the vacated portion of 35th Avenue South is to remain open to pedestrian traffic, and such condition shall run with the land and shall be binding on all parties having or acquiring any right, title, or interest in the land described herein;

NOW, THEREFORE, THE CITY COUNCIL OF THE CITY OF TUKWILA WASHINGTON, DO ORDAIN AS FOLLOWS:

Section 1. Vacation. The following property located in the City of Tukwila is hereby vacated.

All that portion of the right-of-way for 35th Avenue South lying between the southerly margin of South 124th Street and northerly of the north line of Lot 4 of the plat of Donaldson Addition, as recorded in Volume 20 of Plats of page 46, records of King County, Washington, extended easterly to the easterly margin of 35th Avenue South

Section 2. Easements. See Exhibit "A" for easement to the City of Seattle See Exhibit "B" for easement to Piget Sound Energy, Inc See Exhibit "C" for easement to Val Vue Sewer District See Exhibit "D" for easement to King County Water District No 125 See Exhibit "E" for ingress and egress to Assessors Parcels 206360-0005, 0020, 0025, 0030, 0035, and 0036

Section 3. Dutres of City Clerk. The City Clerk is hereby directed to record a certified copy of this ordinance with King County, upon determination by the City Public Works Director that the conditions referenced above have been satisfied.

Section 4. Amendment of Official Street Map. Upon the recording of a certified copy of the ordinance, the City Public Works Director shall amend the City's official street map to be consistent with this ordinance

Section 5. Severability. If any section, subsection, paragraph, sentence, clause or phrase of this ordinance or its application to any person or situation should be held to be invalid or unconstitutional for any reason by a court of competent jurisdiction, such invalidity or unconstitutionality shall not affect the validity or constitutionality of the remaining portions of this ordinance or its application to any other person or situation

Section 6. Effective Date. This ordinance or a summary thereof shall be published in the official newspaper of the City, and shall take effect and be in full force and effect five (5) days after passage and publication as provided by law, provided that the vacation specified above shall not become effective until the conditions contained herein have been fully satisfied and all documents have been recorded with King County Records

PASSED BY THE CITY COUNCIL OF THE CITY OF TUKWILA, WASHINGTON, 15 day of_ Regular Meeting thereof this_

ATTEST/AUTHENTICATED

wen Mmullet Steven M Mullet, Mayor

36

Jable E Cantu, CMC, City Clerk

APPROVED AS TO FORM

B٦ Office of the City Attorney

FILED WITH THE CITY CLERK 10 PASSED BY THE CITY COUNCIL: 10/ PUBLISHED 10/19/0/ EFFECTIVE DATE 10/24/0/ ORDINANCE NO /978

cm ~:t• հԱ 5 **C** œ 5 2002

EXHIBIT "A" TO CITY OF TUKWILA STREET VACATION OF 35TH AVENUE SOUTH.

ÉASEMENT (Overhead and Underground) PM#230410-3-012

THIS BASEMENT GRANTS to the City of Seattle (hereafter referred to as Grantee), its successors and assigns, the right, privilege and authority to install, construct, erect, alter, improve, repair, energize, operate and maintain electric overhead and underground distribution facilities, which consist of poles with braces, guys and anchors, crossatins, transformers, ducts, vaults, manholes, cabinets, containers, conduits, wires and other necessary or convenient appurtenances to make said underground and overhead installations an integrated electric system. All such electric system is to be located across, over, upon and under the following described lands and premises situated in the County of King, State of Washington, to wit.

All that portion of the right of way for 35^{th} Avenue South lying between the Southerly margin of South 124^{th} St and North line of Lot 4 in the plat of Donaldson Addition, as recorded in Volume 20 of Plats at page 46, records of King County Washington, extended Easterly to the Easterly margin of 35^{th} Avenue South, in the City of Tukwila, King County, Washington (Located in the Southwest 14 of Section 10, Township 23 North, Range 4 East of W M)

Together with the right at all times to the Grantee, its successors and assigns of ingress to and egress from said lands across adjacent lands abutting the described easement area for the purpose of installing, constructing, reconstructing, repairing, renewing, altering, changing, patiolling, energizing and operating said electric system, and the right at any time to remove all or any part of said electric system from said lands

Also the right to the Grantee, its successors and assigns, at all times to cut and trum brush, trees of other plants standing or growing upon said lands or adjacent lands which, in the opinion of the Grantee, interfere with the maintenance or operation of the system, or constitute a menace or danger to said electric system

It is further covenanced and agreed that no structure or fire hazards will be erected or permitted within the above described easement area without prior written approval from the Grantee, its successors and assigns; that no digging will be done or permitted within the easement area which will in any manner disturb the facilities or their solidity or unearth any portion thereof, and that no blasting or discharge of any explosives will be permitted within fifty (50) feet of said lines and appurtenances.

The City of Seattle is to be responsible, as provided by law, for any damage through its negligence in the constituction, maintenance and operation of said electric system across, over, upon and under the property granted in this easement or adjacent land thereto.

The rights, title, privileges and authority hereby granted shall continue and be in force until such time as the Grantee, its successors and assigns shall permanently remove said poles, wires and appurtenances from said lands or shall otherwise permanently abandon said electric system, at which time all such rights, title, privileges and authority hereby granted shall terminate.

Éxhibit A

EXHIBIT B"

RETURN ADDRESS: Puget Sound Energy, Inc. Attn: ROW Department PO Box 90868 OBC-11N Bellevue, WA 98009-9869

800154

070

2002

EASEMENT

REFERENCE # GRANTOR INTERNATIONAL GATEWAY EAST LLC GRANTEE PUGET SOUND ENERGY, INC. SHORT LEGAL SW 10-23-04 ASSESSOR'S PROPERTY TAX PARCEL:

EXHIBIT B

For and in consideration of One Dollar (\$1 00) and other valuable consideration in hand paid, INTERNATIONAL GATEWAY EAST LLC, a Washington limited liability company ("Grantor" herein), hereby conveys and warrants to PUGET SOUND ENERGY, INC., a Washington Corporation ("Grantoe" herein), for the purposes hereinafter set forth, a nonexclusive perpetual easement over, under, along across and through the following described real property ("Property" herein) in KING County, Washington

ALL THAT PORTION OF THE RIGHT OF WAY FOR 35TH AVENUE SOUTH LYING BETWEEN THE SOUTHERLY MARGIN OF SOUTH 124TH STREET AND NORTHERLY OF THE NORTH LINE OF LOT 4 OF PLAT OF DONALDSON ADDITION, AS RECORDED IN VOLUME 20 OF PLATS OF PAGE 46, RECORDS OF KING COUNTY, WASHINGTON EXTENDED EASTERLY TO THE EASTERLY MARGIN OF 35TH AVENUE SOUTH.

Except as may be otherwise set forth herein Grantee's rights shall be exercised upon that portion of the Property ("Easement Area" herein) described as follows:

AN EASEMENT AREA TEN FEET IN WIDTH HAVING FIVE FEET ON EACH SIDE OF THE GENTER LINE OF THE NATURAL GAS PIPELINE(S) INSTALLED IN THE ABOVE DESCRIBED REAL PROPERTY.

1/ Purpose. Grantee shall have the right to construct, operate, maintain, repair, replace, improve, remove, enlarge, and use the easement area for one or more utility systems for purposes of transmission, distribution and sale of gas and electricity. Such systems may include, but are not limited to

Underground facilities. Pipes, pipelines, mains, laterals, conduits, regulators and feeders for gas, fiber optic cable and other lines, cables and facilities for communications; semiburied or ground-mounted facilities and pads, manholes, meters, fixtures, attachments and any and all other facilities or apputtenances necessary or convenient to any or all of the foregoing

Following the initial construction of all or a portion of its systems, Grantee may, from time to time, construct such additional facilities as it may require for such systems. Grantee shall have the right of access to the Easement Area over and across the Property to enable Grantee to exercise its rights hereunder. Grantee shall compensate Grantor for any damage to the Property caused by the exercise of such right of access by Grantee

2. Easement Area Clearing and Maintenance: Grantee shall have the right to reasonably cut, remove and dispose of any and all brush, trees or other vegetation in the Easement Area Grantee shall also have the right to control, on a continuing basis and by any prudent and reasonable means; the establishment and growth of brush, trees or other vegetation in the Easement Area.

3. Trees Outside Easement Area. Grantee shall have the reasonable right to cut, trim remove and dispose of any trees located on the Property outside the Easement Area that could, in Grantee's reasonable judgment, interfere with or create a hazard to Grantee's systems. Grantee shall, prior to the exercise of such right, identify such trees and make a reasonable effort to give Granter prior notice that such trees will be out, trimmed, removed or disposed of (except that Grantee shall have no obligation to derify such trees of give Grantor such prior notice when trees are cut, trimmed, removed or otherwise disposed of in response to emergency conditions). Grantor shall be entitles to no compensation for trees cut, trimmed, removed or disposed of disposed of for fine actual market value of merchantable timber (If any) cut and removed from the Property by Grantee, or if Grantee acts unreasonably.

4. Grantor's Use of Easement Area Grantor reserves the right to use the Easement Area for any purpose not inconsistent with the rights herein granted, provided, however, Granter shall not construct or maintain any, buildings, structures or other objects on the Easement Area

5. Indemnity. Grantee agrees to indemnify Grantor from and against liability incurred by Grantor as a result of Grantee's negligence in the exercise of the rights herein granted to Grantee, but nothing herein shall require Grantee to indemnify Grantor for that portion of any such liability attributable to the negligence of Grantor or the negligence of others

6/98 Gas Easement 31736 204074 6. Abandonment The rights herein granted shall continue until such time as Grantee ceases to use the Easement Area, in which event, this easement shall terminate and all rights hereunder, and any improvements remaining in the Easement Area, shall revert to or otherwise become the property of Grantor, provided, however, that no abandonment shall be deemed to have occurred by reason of Grantee's failure to initially install its systems on the Easement Area within any period of time from the date hereof.

7. Successors and Assigns. Grantee shall have the right to assign, apportion or otherwise transfer any or all of its rights, benefits, privileges and interests arising in and under this easement. Without limiting the generality of the foregoing, the rights and obligations of the parties shall inure to the benefit of and be binding upon their respective successors and assigns.

and the second

2002 070 8001545

DATED this day of		, 2001
GRANTOR:	for the second s	
INTERNATIONAL GATEWAY EAST LC, b Sabey Corporation, Manager	x/p/ /p	
BY:	1.J.N	
JAMES N. HARMON CFO Sabey Corporation		. ^
STATE OF WASHINGTON	$///$ \sim	
COUNTY OF KING)	° (d i d j ^	
On this day of	, 2001, before me,	the undersigned, a Notary Public in and for eared JAMES N HARMON, to me known to
be the person who signed as CFO of SABE corporation, that executed the within and fo and voluntary activated deed and the free ar	EY CORPORATION to Man regoing instrument, and ackr id voluntary act and deed of d; and on oath stated that	ager of Infernational Galeway East LLC, the lowledged said instrument to be his/her free INTERNATIONAL GATEWAY EAST LLC for HEwas authorized to execute the said
N WITNESS WHEREOF I have here	ounto set my hand and officia	l seal the day and year first above written
	(Signature of Notary)	
×_//)/,		
and for the second s	(Print or stamp name of No NOTARY PUBLIC in and fo	or the State of Washington, residing
and the second sec	My Appointment Expires	
Notary seal, text and all notations must be inside 1* matricins		л ^а н.
. ¹ 1.100	فتوشق فكر كم في تتو معمد	
	م الم الم الم الم الم الم الم الم الم ال	
		M/s .
		이 가지 않는 것 같은 것 같
		Exhubit B 2/2
		Exhupt B 2/3
		ESHINT BY 2/2
		Exhapit B 2/3
		Exhapt B 2/3

EASEMENT EXHIBIT

GRANTOR, INTERNATIONAL GATEWAY EAST LLC, for and in consideration of One Dollar (\$1 00) and other valuable considerations, the receipt of which is hereby acknowledged, grants and conveys to GRANTEE, VAL VUE SEWER DISTRICT, King County, Washington, a municipal corporation, an easment and right-of-way, over, across, along, through, and under the real property situated in King County, Washington as described on Exhibit A and illustrated on Exhibit B, attached hereto

For the purposes of constructing, installing, reconstructing, replacing, repairing, mantaning and operating a sewer pipeline and lines and all necessary connections and appurtenances thereto, together with the right of ingress and egress therefrom for the purpose of enjoying the easement, and also granting to Grantees and to those acting under or for Grantees the use of such additional area immediately adjacent to the above easement as shall be required for the construction of the sewer pipeline or lines in the easement, such additional area to be held to a minimum necessary for that purpose, and immediately after the completion of the construction and installation, or any subsequent entry upon the easement, Grantees shall restore the premises as near as may be to its condition immediately before such construction or entry.

IN WITNESS WHEREOF, Grantor has hereunder set its hand this a 2001. INTERNATIONAL GATEWAY by Sabey Corporation, Manager fames N. Harmon, CFO of Sabey Corporation TATE OF WASHINGTON COUNTY OF KING

On this day of day of 2001, before me, the undersigned, a Notary Public in and for the State of Washington, duly commissioned and sworn, personally appeared JAMES N. HARMON, to me known to be the person who signed as CFO of SABEY CORPORATION, the Manager of International Gateway East LLC, the corporation that executed the within and foregoing instrument, and acknowledged said instrument to be his/her free and voluntary act and deed and the free and voluntary act and deed of INTERNATIONAL GATEWAY EAST LLC for the uses and purposes therein mentioned; and on oath stated that he was authorized to execute the said instrument on behalf of said INTERNATIONAL GATEWAY EAST LLC.

IN WITNESS WHEREOF I have hereunto set my hand and official seal the day and year first above written.

Printed Name:

MARY A. HALL. STATE OF WASHINGTON NOTARY ----- PUBLIC NY COMMISSION EXPIRES 12-19-01

CIT'S

LEY

010 80

2002

NOTARY PUBLIC in and for Washington, residing at

40

MAA

g \legal\wp\doc\igeast\EASEMENT-Sewer Dist doc

My Appointment Expires:

SANITARY SEWER EASEMENT RECORDING NO. 7508130483 PORTION TO BE EXTINGUISHED

All that portion of the above-referenced sanitary sewer easement, lying Westerly of the Easterly 172 feet of Lot 22, Block 8 of Riverton, a replat of part of Riverside Interurban Tracts, as per plat recorded in Volume 13 of Plats, Page 36, records of King County, Washington.

.....

1

41

2002 070 8001548

and the second

A.

LEGAL DESCRIPTION

RIGHT-OF-WAY VACATION

All that portion of the right-of-way for 35th Avenue South lying between the Southerly margin of South 124th Street and Northerly of the North line of Lot 4 of the plat of Donaldson Addition, as recorded in Volume 20 of Plats of page 46, records of King County, Washington extended Easterly to the Easterly margin of 35th Avenue South

ьē

BITC

2

42

2602 070 8001548

1000

/#

•

EXHIBIT A

Legal Description

Sewer Easement

That part of the Southwest quarter of the Southwest quarter of Section 10, Township 23 North, Range 4 East of Willamette Meridian, King County, Washington,

A 10-foot wide strip of land across Proposed Vacated 35th Avenue South as extended Westerly from Sewer Easement recorded under Recording No 8510250614.

Ext

12 m - 10 10


43

891248

2**6**02 078

and the second s

1



Recording Requested By and EXHIBIT

2002 070 6001546

Document Title(s) (or transactions contained therein). Easement for Water Mains 1 2 З. 4. Reference Number(s) of Documents assigned or released: (on page_____ of document(s)) Grautor(s) (Last name first, then first name and initials International Gateway East LLC, by Sabey Corporation, Manager, 1 2. 3 of document. Additional names on page ____ 5. ា 🕹 Grantee(s) (Last name first, then first name and initials) King County Water District No 125 1 2, з. 4 of document. Additional names on page 5. Legal Description (abbreviated: i.e. lot, block, plat or section, township, range) Portion of the Southwest quarter of the Southwest quarter of Section 10, Township 23 North, Range 4 East, W.M., King County, Washington Additional legal is on page 🖉 of document Assessor's Property Tax Parcel/Account Number N/A The Auditor/Recorder will rely on the information provided on the form The staff will not read the document to verify the accuracy or completeness of the indexing information provided herein. EXH 13

45

EASEMENT FOR WATER MAINS Group Health Cooperative

International Gateway East LLC, by Sabey Corporation, Manager (the "grantor"), for and in consideration of one dollar (\$1.00) and other good and valuable consideration, hereby dedicates, conveys and grants to King County Water District No 125, King County, Washington (the "grantee") and its successors and assigns a permanent casement for water mains and appurtenances thereto under upon and through the following described property situated in King County, Washington, legally described as

See Attached Legal Description and Exhibit

1. That grantee shall have the right without prior institution of any suit or proceeding at law, at times as may be necessary, to enter upon said property and adjoining property owned by the grantor and his assigns and successors to install, lay, construct, renew, operate and maintain mains and necessary facilities and other equipment for the purposes of serving the property and other properties with water and other utility service. The grantee agrees to restore the property to its condition prior to any disturbance from construction, maintenance or repair of such facilities.

2. The grantor covenants that no structure or obstruction, including fences, shall be erected over, upon or within and no trees, bushes or other shrubbery shall be planted in the area of ground for which the easement in favor of grantee has been provided herein

3. This easement and the covenants herein shall be covenants running with the land and shall be binding on the successors, heirs and assigns of both parties hereto.

4 The grantor warrants that the grantor has good title to the above property and warrants the grantee title to and quiet enjoyment of the easement conveyed hereto

Bv

Its.

DATED this & day of

Л

GRANTOR(S):

International Gateway East LLC, by Sabey Corporation, Manager

GXIHIBIT:

46

2001

follows:

(Individual Acknowledgment) STATE OF WASHINGTON 8S, COUNTY OF KING I certify that I know or have satisfactory evidence that ____ (his/her) free and voluntary act for the uses and purposes instrument and acknowledged it to be mentioned in the instrument Dated Signature of Notary Public Title My appointment expires ∞ 000154 (Corporate Acknowledgment) STATE OF WASHINGTON 2602 070 SS COUNTY OF KING I certify that I know or have satisfactory evidence that _James N. Harmon acknowledged it as the Chief Financial Officer of Sabey Corporation, Manager of to be the free, and voluntary act of such party for the uses and purposes mentioned *International Gateway East LLC in the instrument. June 6, 2001 Dated MARY A HALL Signature of STATE OF WASHINGTON Notary Public NOTARY ---- PUBLIC MY COMMISSION EXPIRES 12-19-01 Title Notary Public 12/19/01 My appointment expires 47

LEGAL DESCRIPTION

WATER MAIN EASEMENT

That portion of the Southwest quarter of the Southwest quarter of Section 10, Township 23 North, Range 4 East of the Willamette Meridian, King County, Washington, lying within a 15-foot wide strip of land, being 7.50 feet both sides of the following described line.

BEGINNING at the intersection of the South right-of-way line of South 124th Street and a line 25 feet West of, perpendicular to, and parallel with the Eastright-of-way line of Proposed Vacated 35th Avenue South:

THENCE along said parallel line, South 01⁸46' 02" West, 280 00 feet; THENCE South 88° 13' 58" East, 25'00 feet,

THENCE North 88° 13' 58" West, 25.00 feet;

THENCE along said parallel line, South 01%46' 02" West, 114 00 feet,

THENCE South 88° 13' 58" East; 25.00 feet;

THENCE North 88° 13' 58" West, 25:00 feet;

THENCE along said parallel line, South 01° 46' 02" West, 36:78 feet

THENCE North 88° 13' 58" West, 25 00 feet;

THENCE South 88° 13' 58" East, 25.00 feet;

cm

800154

070

2002

THENCE along said parallel line, South 01° 46' 02" West, 7.00 feet;


THENCE South 43° 13" 58' East, 14.14 feet to a line 15 feet West of, perpendicular to, and parallel with said East right-of-way line,


THENCE along said parallel line, South 01° 46' 02" West, 125 49 feet;

THENCE South 88° 13' 58" East, 15.00 feet; THENCE North 88° 13' 58" West, 15.00 feet; THENCE South 01° 46' 02" West, 40 85 feet to a point of terminus, said point being the intersection of said 15-foot offset line and the extension Easterly of the South line of Lot 3 of Donaldson Addition recorded in Volume 20 of Plats, page 46, King County, Washington.

The sidelines of said strip shall be shortened or lengthened to meet at angle points and to terminate on the extended said South right-of-way line of South 124th Street, the extended South line and East line of said Lot 3 of Donaldson Addition, and the East right-of-way of Proposed Vacated 35th Avenue South.

EXHIB







October 12, 2021

Ms. Nora Gierloff City of Tukwila, DCD Director 6300 Southcenter Blvd., #100 Tukwila, WA 98188

Dear Ms. Gierloff,

Sabey Corporation ("Sabey") is asking for your approval to physically secure our Intergate East Campus with perimeter fencing due to the ongoing, frequent crime and theft from our staff and customer vehicles. We are attaching a 12-month review of the crime incidents to illustrate the magnitude of problems we have experienced.

We would appreciate your review and consideration of the following:

In Ordinance No. 1978 (yr. 2002) pedestrian access is discussed in the summary prior to the Ordinance but is not included as a condition of the Ordinance. We are attaching a copy of Ordinance No. 1978 (yr. 2002) for ease of reference.

Secondly, in 2005 Ordinance No. 2101 vacation of South 124th Street from the City of Tukwila was approved which makes this a private street to be maintained by Sabey without public access. We are attaching a copy of Ordinance No. 2101 for ease of reference as well.

We are also attaching a copy of the site plan we would like to move forward to a preapplication meeting with the City of Tukwila to gain concept approval to secure access to our site because of the safety concerns mentioned above. Please let me know if you have any questions or need clarification on this request.

Sincerely,

SABEY CORPORATION

Milal Jun

Mikel Hansen Chief Operating Officer

Incident Reports

INCIDENT REPORT



Date of Incident: 11/26/2020

Time of Incident: 2300-2330

1. Client: Sabe	ey Data Center	Address: 3355 S	S. 120 th Pl. Tukwila, WA	Post: Mobile						
2. Client Notifi	ed:	Time :0730	Name: Property Management	Title: Property Management						
		Email List								
3.G4S Notified:		Time: 0730	Name: Joseph Breaux	Title: Sr District Manager						
4. Police Notified:		Time:	Officers Name:	RPT#/Badge#:						
5. Persons Involved/Witnesses (Insert category of relationship letter opposite name in * column. A. Employee B. Client Employee C.										
Other)										
*	Name/Position Title	e Pl	hone # Organ	nization Name & Address						
А										
В										
C.										
6. Description of	of Property/Equipment DHS	Black gate, Barrica	de wire.							
				ade was cut as well as the yellow chain on						
the black DHS g	ate. When reviewing the footag	ge, we see a subject	comes down the hill from the black	DHS gate down the hill. He is riding a						
motorcycle. He stops on the other side of the barricade for a few minutes and then drives through it. He drives around the parking lot around										

the black DHS gate. When reviewing the footage, we see a subject comes down the hill from the black DHS gate down the hill. He is riding a motorcycle. He stops on the other side of the barricade for a few minutes and then drives through it. He drives around the parking lot around building 4. Goes behind building 4 and up the hill towards the south upper parking. Eventually leaving through the top exit towards the residential area.

Signature: Capt A Hair Date: 11.27.2020 Time: 1000
--



Date of Incident: OCT.5.2020

Time of Incident: 22:50 PM

1. Client: Sab	bey	Address: 12500 Tukwila International BLVD Tukwila, WA 98168			Post: Sabey Closed Patrol
2. Client Notified: Yes		Time: 23:00 PM	Name: Security C	aptain	Title: Captain Andrew Hair
3. G4S Notified: No		Time: N/A	/A Name: N/A		Title: N/A
4. Police Notified: No		Time: N/A Officers Name: SGT Sean Rit		ame: SGT Sean Rita	RPT#/Badge#:
5. Persons Invo Other)	olved/Witnesses (Insert catego	ry of relationshi	p letter opposit	e name in * column. A	. Employee B. Client Employee C.
*	Name/Position Title		Phone # Organ		nization Name & Address
А	SGT S. Rita		06-390-0748 Sabe		y Closed Patrol Security
В					
C					

6. Description of Property/Equipment.

Department of Homeland Security, North parking lot. Items damaged: Several Davey Tree trucks, locks appeared to have been drilled out. I am unsure of what items were stolen, if any.

7. Description of incident.

On 5 October 2020 at approx. 22:50 PM I arrived at the Department of Homeland Security and was beginning routine patrol when I found a cargo door open on one of the Davey Tree vehicles parked in the north paid parking area. I inspected the door and found the lock had appeared to have been broken by a drill. I also found a yellow container with drill bits in the middle of the road and placed it back into the cargo door. After this initial discovery, I inspected all of the vehicles on the property and found that at least 5 appeared to have been broken into or had locks that appeared drilled out. I contacted Captain Andrew Hair and informed him of this, and he stated to take pictures and he would inform property management in the morning. Davey Tree was notified when they arrived in the morning. I took pictures of each lock I found to be broken and each cargo door that was broken in to and will attach them along with this report.

Signature: SGT S. Rita	Date: 10.6.2020	Time: 6:30 AM
------------------------	-----------------	---------------



Date of Incident: OCT.6.2020

Time of Incident: 4:45 AM

1. Client: Sabe	ey .	Address: 12	2500 Tukwila In	Post: Sabey Closed Patrol		
		Tukwila, WA 98168				
2. Client Notified: Yes 3. G4S Notified: No 4. Police Notified: No		Time:	Name:		Title: Security Captain	
		4:50 AM	Captair	Andrew Hair		
		Time: N/A	Name: 1	N/A	Title: N/A	
		Time: N/A	Officers	Name: SGT Sean Rita	RPT#/Badge#:	
5. Persons Invol Other)	lved/Witnesses (Insert catego	(Insert category of relationship letter opposite name in * column. A. Employee B. Client Employe		A. Employee B. Client Employee C.		
*	Name/Position Title	•	Phone # Organ		nization Name & Address	
А	SGT S. Rita		206-390-0748 Sabe		ey Closed Patrol Security	
В						
C						
6. Description o	f Property/Equipment.	•		·		

6. Description of Property/Equipment.

Department of Homeland Security, North parking lot. Gate between DHS and IGE appears to have been rammed.

7. Description of incident.

On 8 September 2020 at approx. 2:45 AM I was patrolling IGW when I noticed a vehicle exit DHS property from the north parking lot. Upon entering the paid parking lot, I discovered the gate between IGE and DHS appears to have been rammed. The gates were in the closed position during my previous patrols, and I found scrape wounds of the gate on the pavement. I patrolled the property and did not notice any other property damage or items missing. I informed Captain Hair of this incident.

Signature: SGT S. Rita	Date: 10.6.2020	Time: 5:05 AM
------------------------	-----------------	---------------



Date of Incident: FEB.8.2021

Time of Incident: 02:30 AM

1. Client: Sabo	ey	Address: 12500 T	ukwila International BLVD	Post: Sabey Closed Patrol	
		Tukwila, WA 9816	58		
2. Client Notifie	ed: Yes	Time:	Name:	Title: Captain Andrew Hair	
		06:45 AM	Security Captain		
3. G4S Notified: No		Time: N/A	Name: N/A	Title: N/A	
4. Police Notifie	ed: Yes	Time: 02:30 AM Officers Name: SGT Sean Rita		RPT#/Badge#:	
5. Persons Invo	lved/Witnesses (Insert catego	y of relationship letter opposite name in * column. A		. Employee B. Client Employee C.	
Other)					
*	Name/Position Title	Phone # Organ		nization Name & Address	
А	SGT S. Rita	206-3	90-0748 Sabe	ey Closed Patrol Security	
В					
С					
6. Description of	of Property/Equipment.				

Department of Homeland Security, North parking lot

7. Description of incident.

On 8 February 2021 at approx. 02:30 AM while the Department of Homeland Security north parking lot and noticed two unattended bags. One was a black suitcase and the other was a pink and grey backpack. I did not observe these bags on previous patrols. I inspected the Davey Tree and Kemp West vehicles and found no signs of theft or damage and did not see any persons on or near the property. I then contacted the Tukwila Police Department and asked for an officer to inspect the bags. I received a call from Officer Hodgson who informed me TPD generally does not take property into their custody unless it is involved in a crime and to contact him if there is anything suspicious after I inspected the bags. I carefully opened and briefly inspected the bags. I found articles of clothing, personal hygiene items and children's toys. I have attached pictures of the contents. The bags are located near the forested area, on the middle level of the parking area. The bags are located near a noticeable footpath into the forested area. I did not see any individuals or signs of a campsite in the area. End of report.

F	1	1	
	Signature: SGT S. Rita	Date: 02.8.2021	Time: 6:30 AM



Date of Incident: NOV.8.2020

Time of Incident: 19:40 PM

1. Client: Sab	Address: 12500 Tukwila International BLVD Tukwila, WA 98168			Post: Sabey Closed Patrol		
2. Client Notified: Yes		Time: 06:30 AM		Name: Security Captain		Title: Captain Andrew Hair
3. G4S Notified: No		Time: N/A	e: N/A Name: N/A			Title: N/A
4. Police Notified: Yes		Time: 19:50 PM		Officers Name: SGT Sean Rita		RPT#/Badge#:
5. Persons Involved/Witnesses (Insert catego Other)		ry of relations	ship le	tter opposit	e name in * column. A.	. Employee B. Client Employee C.
*	Name/Position Title	1	Phone #		Organization Name & Address	
А	SGT S. Rita		206-390-0748 Sab		Sabey	Closed Patrol Security
В						
С						

6. Description of Property/Equipment.

Department of Homeland Security, North parking lot, Davey Tree Truck and Kemp West Truck

7. Description of incident.

On 8 November 2020 at approx. 19:40 PM I was patrolling the Department of Homeland Security north parking lot and noticed a Kemp West truck had a slightly open cargo door. I inspected the door and truck and noticed another open door and one door that had the handle extended. I contacted Officer Singh and asked if he had noticed this while he was patrolling DHS. I inspected the truck for approximately 3-5 minutes before resuming patrol where I noticed a door open on a Davey Tree truck. This door had been secured and I had a view of this truck during my initial patrol. I then contacted Officer Singh for backup and Tukwila PD to inform them we may have someone actively breaking into the trucks. Officer Singh and I patrolled the area including IGW, IGE and the surrounding roads and did not see any signs of suspicious activity or any persons. Tukwila PD arrived at approx. 2010hrs and inspected the vehicle. He informed me to have the employees of Davey Tree and Kemp West contact them in the morning if anything was stolen. I also attempted to contact Sarah Marques at approx. 2010hrs to see if she was able to pull up the video stream but was unable to get ahold of her. Pictures are attached. The officer informed me there is no incident number for this since no report was taken. End of report.

Signature: SGT S. Rita	Date: 11.8.2020	Time: 6:30 AM
------------------------	-----------------	---------------



Date of Incident: SEP.8.2020

Time of Incident: 2:45 AM

1. Client: Sab	Address: 12500 Tukwila International BLVD Tukwila, WA 98168		Post: Sabey Closed Patrol			
2. Client Notified: Yes		Time: 6:25 AM		Name: Property Management		Title: Ron L., Captain Andrew Hair
3. G4S Notified: No		Time: N/	N/A Name: N/A			Title: N/A
4. Police Notifi	ed: No	Time: N/A Officers Name: SGT Sean		ame: SGT Sean Rita	RPT#/Badge#:	
5. Persons Invo Other)	lved/Witnesses (Insert catego	ry of relati	onship le	etter opposit	e name in * column. A	. Employee B. Client Employee C.
*	Name/Position Title		Phone # Organ		Organ	ization Name & Address
А	SGT S. Rita		206-3	206-390-0748 Sabe		Closed Patrol Security
В						
С						

6. Description of Property/Equipment.

Department of Homeland Security, North parking lot. Item stolen: Davey Tree work trailer

7. Description of incident.

On 8 September 2020 at approx. 2:45 AM I arrived at the Department of Homeland Security and was beginning routine patrol when I found the lower gate between IGE and DHS had been cut open. The chain had been cut, and one side of the gate open. I contacted SDC5 and asked the security officer if they noticed any suspicious/unknown persons or vehicles on the property, they stated they had not. I conducted a thorough patrol of the vehicles and found no signs of damage or attempted break-ins. I informed Captain Hair so we could review the security footage. After reviewing the footage, we noticed a truck enter IGE property at approx. 1:27 AM and turn its lights off. The truck exited through IGE property at approx. 1:38 AM. The truck appeared to be towing a yellow Davey Tree trailer. I informed property management through the on-call engineer at approx. 6:25 AM of this. I spoke with Ron L, who stated he would inform the appropriate contacts.



Date of Incident: 06.23.2021

Time of Incident: 04:30 AM

1. Client: Sabey	Address: 3355 120	0 th Pl S Tukwila, WA 98168	Post: Sabey Closed Patrol	
2. Client Notified: Yes	Time: Name:		Title: Captain Andrew Hair	
	06:45 AM	Security Captain	-	
3. G4S Notified: No	Time: N/A	Name: N/A	Title: N/A	
4. Police Notified: Yes	Time: 04:40 AM Officers Name:		RPT#/Badge#:	
5. Persons Involved/Witnesses (Insert catego Other) S/O Lemlemayehu	ry of relationship le	etter opposite name in * colun		
Other) S/O Lemlemayehu	e Ph	10ne # 0	nn. A. Employee B. Client Employee C.	
Other) S/O Lemlemayehu * Name/Position Title	e Ph	10ne # 0	nn. A. Employee B. Client Employee C. Organization Name & Address	

6. Description of Property/Equipment.

Upper South Parking, Toyota Highlander WA BQH2183, Hyundia Sonata WA AKW8039.

7. Description of incident.

On 23 June 2021 at approx. 04:30 AM I received a call from the S/O Lemlemayehu at SDC5 reporting that two individuals appeared to be peering in and attempting to break into vehicles at the SDC5 upper parking lot. The S/O informed me one individual appeared to run into the adjacent forest and another individual left the camera frame.

I responded and upon my arrival noticed one individual (male, brown hair, dark pants, approx. 5'10 - 5'11, 175 lbs, light heavy scruff). The individual was also wearing heavy duty gloves. I did a quick inspection of the vehicles and noticed two gas panels were slightly open on two vehicles. I did not notice any other damage upon arrival. After inspecting the vehicles in the parking lot, I spoke with the individual described above and he asked where the "SAR'S" was. I asked what he was doing here, which he said he was lost. I informed him he needed to leave and the individual left without issue. I patrolled IGE II found no signs of damage or theft in any of the vehicles.

I returned to SDC5 and entered the office to review the footage to see if any theft or damage occurred. While in the office, a red sedan pulled up and an individual wearing a face mask and dark clothing got out of the vehicle and started looking at parked vehicles. I told the S/O to call 911 and I went outside. As I went up the stairs I shouted "Hey!" the individual got back into the vehicle and the vehicle took off at a high rate of speed. I was able to get a partial plate and I believe the plate was: BQS1538. The vehicle was a small, two door red sedan (possibly a Toyota). The individual who was driving appeared to be Asian, black hair and wore a face mask. The individuals left the property and did not return for the rest of my shift.

Upon inspection of the vehicles and review of the security footage, we discovered the individuals were able to break into the S/O's car and stole her wallet. The individual shot out her window with a handgun of some sort at about 0505. The other vehicle broken into was a Hyundai Sonata (LIC: AKW8039) at about 0425. The individuals accessed the interior of the vehicle and the trunk. I am unsure of what was stolen. Captain Hair will be filing the report with Tukwila Police Department. S/O Lemlemayehu filed her own report with the police department and was the main contact with Tukwila Police for this incident as it occurred.

Signature: SGT S. Rita Date: 06.23.2021 Time: 6:40 AM		Signature: SGT S. Rita	Date: 06.23.2021	Time: 6:40 AM
---	--	------------------------	------------------	---------------



Date of Incident: June.29.2021

Time of Incident: 04:30 AM

1. Client: Sabe	2 y	Address: 3433 S		a, WA 98168	Post: Sabey Closed Patrol	
2. Client Notified: Yes		Time:	Name:		Title: Captain Andrew Hair	
06:45 A		06:45 AM	06:45 AM Security Captain		-	
3. G4S Notified: No		Time: N/A	Name: N/A		Title: N/A	
4 D.P. N. 46	J. X7	Times 04.50 AM	Off		DDT#/D = 1 = . #.	
4. Police Notifie			Time: 04:50 AMOfficers Name: SGT Sean Rita		RPT#/Badge#:	
5. Persons Invol	ved/Witnesses (Insert catego	ory of relationship le	etter opposite 1	name in * column. A	A. Employee B. Client Employee C.	
Other)	· _	• -	••			
*	Name/Position Title	e Pł	Phone # Organ		nization Name & Address	
А	SGT S. Rita		390-0748	Sabe	y Closed Patrol Security	
В						
С						
6. Description of	of Property/Equipment.					
Intergate East F	Facilities mailbox (near BLDO	G 4)				
7 Decemintion	A		-	-		

7. Description of incident.

On 29 June 2021 at approx. 04:28 AM I received a call from SDC5 regarding an individual who appeared to be breaking into the mailbox near BLDG 4. Upon my arrival to IGE I found the mailbox open, with it appearing to be forced open. A silver Nissan sedan also drove by the individual and may be involved. After arriving to IGE I noticed the Nissan leaving the parking lot near BLDG 1 and was able to obtain the LIC: BVZ9593. I spoke with some employees at Sahale who were outside and reported to me they saw a woman walking near the mailboxes and leaving the property.

I noticed this individual walking on E Marginal Way by IGE II. I was able to speak with her momentarily. She stated she got lost and turned around and saw the silver Nissan but stated she had no association. After speaking with SDC5, it was determined that it appeared a female described wearing a black top, jean shorts and a green bag was on camera breaking into the mailbox, and the Nissan driving by her while she was at the mailbox. This appears to be the same female I had spoken with.

When I was speaking with her, the Nissan drove by and parked off the side of the road and watched our interaction. At this point I returned to my vehicle, feeling unsafe and left the area. SDC5 called Tukwila PD to inform them of the incident and has the incident number. The last direction the woman was walking was southbound on 37th Ave S. The woman I spoke with is described as a Hispanic female, approx. 5'6, wearing a black tank top, jean shorts, a white face mask and carrying a green bag.

Captain Hair arrived at approx. 0500hrs and took pictures of the mailbox. I informed him of the situation further.

END OF REPORT

 Signature: SGT S. Rita
 Date: 03.29.2021
 Time: 6:30 AM



Date of Incident: 6/25/2021

Time of Incident: 1450

1. Client: Sabe	ey Data Center	Address: 3355	S. 120 th Pl. Tu	ıkwila, WA	Post:SDC building 5	
2. Client Notifie	ent Notified: Yes Time:20		000 Name: Jerry Himmelsbach		Title: Facilties Engineer	
Fire 3.G4S Not	ified: Yes	Time: 2114	Name: And	rew Hair	Title: Site Superviser	
4. Police Notifie	ed: Yes	Time : 2023	Officers Name: Jessica Armstrong		RPT#/Badge#:	
5. Persons Invo Other)	olved/Witnesses (Insert catego	ry of relationship l			. A. Employee B. Client Employee C.	
*	Name/Position Title	e P	hone #	Org	anization Name & Address	
А	S/O Kenneth Adan	n 206-'	730-3809	Sabey Data C	nter 3355 S. 120 th Pl. Tukwila, WA	
В	S/O Shawn Singh	206-2	390-0748	Sabey Data C	enter 3355 S. 120 th Pl. Tukwila, WA	
C.	Gerald Hemmelsbac	ch 206-9	919-0172			
7. At about 200 at our video for ST. It then stop wait for the ma about 1453. Th plate number o At about 2023 ' Singh. At 2040 van. We were t	otage to find out what time the os next to the mail boxes and a nilman to leave site at about 14 ey then take all the mail that of the van B79437F. Tukwila Police was contacted she came down to the Seurity	ilboxes had been be e boxes were broke apparently sees the 450 before opening was in the boxes. A . At about 2031 Jes Office to review th as reported stolen	en into. At ab mailman dri the mailbox t about 1455 ssica Armstro he video that and that it w nat had happo	out 1447 a white va ve on site and proc with some type of t they leave property ong from TPD arriv we had as well as th as seen at a Koles.	arald Hemmelsbach. I then started to look n is seen to enter the property from 120 th ced to park next to Building 1. They then ool that is handed to the female subject at y on 120 th ST. We were able to get the ed on site and made contacte with S/O ne picture of the licence plate of the white When I had all the information that I	

Signature: Kenneth J. Adam II Date: 6/28/2021 Time: 0635



Date of Incident:7/3/2021

Time of Incident: 1806

1. Client: Sabey Data Center	Address: 3355	S. 120 th Pl. Tukwila, WA	Post:SDC building 5			
2. Client Notified: Yes	Time :1806	Name: Anthony Rowe	Title: Night Engineer			
Fire 3.G4S Notified: Yes	Time: 1823	Name: Andrew Hair	Title: Site Superviser			
4. Police Notified: Yes	Time : 1818	Officers Name: T. Matsuyuama	RPT#/Badge#: Case Number 21-3359			
		Patrol Division				
5 Dangang Involved/Witnesson (Incent	Dersons Involved/Witnesses (Insert cotagory of relationship latter apposite name in * column A. Employee R. Client Employee C.					

5. Persons Involved/Witnesses (Insert category of relationship letter opposite name in * column. A. Employee B. Client Employee C. Other)

*	Name/Position Title	Phone #	Organization Name & Address
Α	S/O Kenneth Adam	253-970-5341	Sabey Data Center 3355 S. 120th Pl. Tukwila, WA
В	Engineer Anthony Rowe	206-496-9209	Sabey Data Center 3355 S. 120th Pl. Tukwila, WA
C.			

6. Description of Property/Equipment. Mailboxes broken into again

7. Description of incident

At 1809 I was waved down by Anthony Rowe as the mailboxes had just been broken into and the van was leaving as I was pulling up. When I whent into the video to see what time and were they came from, I found them on camera at 1806 as they were turning into the property from 120th. They then arrive at the mailbox at 1807 and proceed to take whatever mail was in the boxes. We see two suspects exit the van, Toyota plate number 397-XSO or Q one Black male and one Black female. They then walk up to the mailbox and act like they belong and open the boxes. At 1809 they leave the mailbox with what they were able to grab and leave site. As they were leaving I was pulling up and seen them leaving. At that time I seen that the mailboxes were open again and I know they were not open when I drove by a few minuts before. At 1812 I started to look at footage to have it ready when the TPD showed up. We then called them at 1818. They arrived on site at 1900 and that is when I gave them all the info that I had gathered.

Signature: S/O Kenneth J.	Date: 7/3/2021 Time: 1915
Adam II	



Date of Incident: FEB.24.2021

Time of Incident: 23:05hrs

Sabey Security

1. Client: Sab	ey		ress 3355 s 120 th PL vila, WA 98168		Post: Sabey Closed Patrol
2. Client Notifie	ed: Yes	Time: 23:05hrs	Name: MS S/O Fi	ırost	Title: Security Officer
3. G4S Notified	l: Yes	Time: 23:05h			Title: Security Officer
4. Police Notifie	ed: N/A	Time: N/A	Officers N	ame:	RPT#/Badge#:
5. Persons Invo Other)	olved/Witnesses (Insert catego	ry of relationsh	ip letter opposit	e name in * column. A	. Employee B. Client Employee C.
*	Name/Position Title		Phone #	Organ	ization Name & Address
А	S/O Peneueta		06-390-0748	Sabe	y Closed Patrol Security
В	S/O Furest N/A		Α	Microsoft Security	

206-730-3809

C S/O Ali 6. Description of Property/Equipment.

Inter Gate East BLDG 5 SE park. lot

7. Description of incident.

On Feb.24.21 at approx. 2300 hrs., I arrived at IGE 5 SE park. Lot to find two cars in the parking lot. The first car I noticed was a Ford diesel truck that had a man inside with the car running. Thinking it was a tenant technician I had moved on to the next car that I seen which was a white minivan. The pilot lights being on I had initially thought the car belonged to a security guard or employee of bldg. 5 so I had circled the parking lot. Coming back to the van I had discovered 3 gasoline tanks underneath the Microsoft owned vehicle and that some type of fluid was leaking from under the vehicle. When I got out of the vehicle to further inspect, I found a man hiding behind the van, trying to avoid me. Immediately I tell him to leave and radio Sabey front desk security to inform the Microsoft security guard of the event and to make his way down to the parking lot. As I am parked in front of the van talking to S/O Fasil, the man in the truck speeds out of the parking lot and makes his way to the parking lot of IGE II. I get out of the car and am talking to the man that is taking his time getting into the van to buy time for the Microsoft guard to get to the scene. I take pictures of the man and the plates of the minivan. The truck speeds from the IGE II lot, back to the IGE 5 SE parking lot and tries to ram the Sabey vehicle out of the way for the minivan to have room to flee the scene. I back out of the way slowly, as to still buy time for the MS security guard to get the plates of the truck, as he only had plates installed on the back of his truck. But before the MS guard could get to the scene, I had backed up enough for the Minivan to get out and both cars fled the scene. No one was hurt, the only damage to property was the MS owned vehicle, and the pics that I have taken of the mini van was given to the MS guard for his reports.

The build of the man in the Minivan was an older white gentleman early to late 50's, and the man in the truck was a middle aged white man red hair he never exited his vehicle so the description is what was seen from the truck window.

Signature: Officer Peneueta Dat	Date: 02.8.2021	Time: 6:30 AM



Date of Incident: May.27.2021

Time of Incident: 18:10 AM

1. Client: Sabey		Address: 3355 S 120 th pl, Tukwila, WA 98168		Post: Sabey Closed Patrol	
2. Client Notified: No		Time:	Name:		Title: Captain Andrew Hair
		16:10	Security Capta	ain	_
3. G4S Notified: Yes		Time: N/A	Name: N/A		Title: N/A
4. Police Notif	ïed: Yes	Time : 16:20	Officers Name	:	RPT#/Badge#:
5. Persons Inv Other)	volved/Witnesses (Insert catego	ry of relationship l	etter opposite na	me in * column. A	. Employee B. Client Employee C.
*	Name/Position Title	e Pl	hone #	Organ	ization Name & Address
А	S/O Singh	206-4	407-4852	U	V Closed Patrol Security
В					
С					
6. Description of Property/Equipment.					
Sabey Data Center, Providence Upper parking lot					
7. Description of incident.					

On 27 May 2021 at approx. 18:10, I was recently clocked in and briefed by S/O Adam about a possible stolen catalytic converter in upper SDC 5 parking lot. I get a call from Josh Simpson from providence that his car got broken into. I arrive to Josh in the back-parking lot of Providence at 18:17 and documented my findings. His car is a grey Subaru WRX which appeared to have had the passenger's side window smashed in. Josh stated that the thief may have taken an old phone from the center console. I then give Josh the number for Tukwila PD non-emergency to make a report. Tukwilla PD Arrived at 1640 to speak with Josh Simpson.

Signature: S/O Singh	Date: 05.27.2021 Time: 16:10
----------------------	--------------------------------



12201 Tukwila International Boulevard, 4th Floor Seattle, WA 98168-5121 Phone: 206-281-8700 Fax: 206-282-9951

INCIDENT REPORT Email to Incident@sabey.com ASAP

Date of Incident:	Time:	Report Prepared	By:
05/27/2021	4:45pm	Mike Anderson	
Type of Incident (Personal Injury?): Was Medical Attention Required/Administered:			
Type of Incident (Property Damage?):Auto Theft and Vandalism_ What Property Was Damaged: Auto/Theft			
Other Incident (please explain)			
Location of Incident:IGE and IGE II Weather conditions:Rain/Sun Mix			
Police Report: Yes Filed by Josh Simpson Officer Name: Case Number:		Case Number:	
with Providence Infusion Pharmacy – Report number and information being obtainedTBDTBD			TBD
Pictures or Video Taken?			

Description of Incident (Include a Complete List of Loss) Attach additional pages if necessary

IGE II Incident: On 27 May 2021 at approx. 18:40, I was finishing my first patrol of IGE II and discovered a CellNetix car with a broken window. Appears to be a hole in the window, rest of the window is still intact. The car is a grey Pontiac Vibe license plate number B99862R; vehicle ID: 971NX. This was discovered after two previous incidents on IGE the same day that had to do with cars being broken into.


Discovered that this vehicle was not on any cameras.

End of report.

IGE Incident: On 27 May 2021 at approx. 18:10, I was recently clocked in and briefed by S/O Adam about a possible stolen catalytic converter in upper SDC 5 parking lot. I get a call from Josh Simpson from providence that his car got broken into. I arrive to Josh in the back-parking lot of Providence at 18:17 and documented my findings. His car is a grey Subaru WRX which appeared to have had the passenger's side window smashed in. Josh stated that the thief may have taken an old phone from the center console. I then give Josh the number for Tukwila PD non-emergency to make a report. Tukwilla PD Arrived at 1640 to speak with Josh Simpson.

MA: These incidents were tracked after the fact there were no visible plates on the suspects vehicle. SDC Security is still investigating to find any additional information. Cellnetix has been notified at this time and I am working on an email to Providence after I finish this incident report. I have attached the links to the videos that I was sent and will upload anything additional I find on this email chain.





Contact Involved

Name:	Address:		
Home Phone:	Work Phone:		
Reason for visit?			
What was your involvement in the incident?			
Where were you located at the time of the incident?			

Witness Information

Name:	Address:	
Home Phone:	Work Phone:	
What was your involvement in the incident?		
Where were you located at the time of the incident?		
What did you see?		

Witness Information

Name:	Address:	
Home Phone:	Work Phone:	
What was your involvement in the incident?		
Where were you located at the time of the incident?		

Witness Information

Name:	Address:	
Home Phone:	Work Phone:	
What was your involvement in the incident?		
Where were you located at the time of the incident?		
What did you see?		



12201 Tukwila International Boulevard, 4th Floor Seattle, WA 98168-5121 Phone: 206-281-8700 Fax: 206-282-9951


INCIDENT REPORT Email to Incident@sabey.com ASAP

Date of Incident:	Time:	Report Prepared By:	
0800		Mike Anderson	
Type of Incident (Personal Injury?):	Was M	Iedical Attention Required/Administered:	
Type of Incident (Property Damage?):Yes Stolen		at Property Was Damaged: _Catalytic Converter	
Other Incident (please explain)			
Location of Incident:	Weathe	r conditions:	
Police Report: No	Officer Name:	Case Number:	
Pictures or Video Taken? No			

Description of Incident (Include a Complete List of Loss) Attach additional pages if necessary

We received a report this morning that an employee of Sahale Snacks had their catalytic converter stolen from off their vehicle while it was parked at work . It was a Silver Toyota Prius , between the hours of 5:30am and 6:00pm on 11/4/2020 attached is a map of the parking spot that they were parked in . I am not sure if we have any camera footage of that exact location but if you could please review the cameras during that time to see if we can narrow down a suspect. The red dots are where the 2 PM cameras are located the yellow dot is where the car was parked. There was no police report filed , they didn't know what was wrong with the vehicle when they got in it and drove it to the car repair shop then today they were told by the dealership that the catalytic converter had been cut out .





Contact Involved

Name:	Address:	
Home Phone:	Work Phone:	
Reason for visit?		
What was your involvement in the incident?		
Where were you located at the time of the incident?		

Witness Information

Name:	Address:	
Home Phone:	Work Phone:	
What was your involvement in the incident?		
Where were you located at the time of the incident?		
What did you see?		

Witness Information

Name:	Address:	
Home Phone:	Work Phone:	
What was your involvement in the incident?		
Where were you located at the time of the incident?		

Witness Information

Name:	Address:		
Home Phone:	Work Phone:		
What was your involvement in the incident?			
Where were you located at the time of the incident?			
What did you see?			



Date of Incident: FEB.12.2021

Time of Incident: 18:30 PM

1. Client: Sabey		Address: 12500 T	ukwila International BLVI	Post: Sabey Closed Patrol
	-	Tukwila, WA 9816	58	
2. Client Notif	2. Client Notified: NO		Name:	Title: Captain Andrew Hair
		18:30 PM	Security Captain	-
3. G4S Notified: NO		Time: N/A	Name: N/A	Title: N/A
4. Police Notified: Yes		Time: 18:30 PM Officers Name: S/O Singl		gh RPT#/Badge#:
5. Persons Inv	volved/Witnesses (Insert catego	ry of relationship le	etter opposite name in * c	olumn. A. Employee B. Client Employee C.
Other)	_			
*	Name/Position Title	e Ph	one #	Organization Name & Address
А	S/O Singh		07-4852	Sabey Closed Patrol Security
В				
С				
6. Description	of Property/Equipment.		1	
-	ett			

Department of Homeland Security, main entrance

7. Description of incident.

On 12 February 2021 at approx. 18:30 PM, I drove to the main entrance of DHS after patrolling IGE II and I immediately notice a man with a black jacket and blue jeans on the property. I approached the man and after a brief conversation, it was clear that he was under the influence. I asked if he needed any assistance or directions, but he was incoherent. He walked away from me and began defecating in the bushes. I called Tukwila non-emergency and they sent Officer Wells to scene. After talking to him for a bit, Officer Wells called an ambulance and they took him off the scene at 1920. No other issues or property damage. Case number: 21-730. End of report.

Signature: S/O Singh	Date: 02.12.2021	Time: 6:30 PM
----------------------	------------------	---------------



Date of Incident: 2/20/2021

Time of Incident: 2030-0100

1. Client: Sabey Data Center	Address: 3355	S. 120 th Pl. Tukwila, WA	Post:SDC building 5
2. Client Notified: 2/22/2021	Time : 1600	Name: Ryan Monson	Title: Operations Manager
3.G4S Notified: 2/22/2021	Time: 1600	Name: Brandon Varice	Title: Security Officer
2/23/2021	0600	Andrew Hair	Title: Secuirty Supervisor
4. Police Notified: N/A	Time:	Officers Name:	RPT#/Badge#:

5. Persons Involved/Witnesses (Insert category of relationship letter opposite name in * column. A. Employee B. Client Employee C. Other)

*	Name/Position Title	Phone #	Organization Name & Address
А	N/A		
В			
C.			

6. Description of Property/Equipment. Multiple Vehicles in Upper South Parking.

7. Description of incident: On 02/20/21 at or about 2030 till 0045 on 2/21/2021 a suspect was prowling vehicles in the upper sourth parking. Subject was wearing a black hooded sweatshirt and dark colored pants. At about 2100 he put on an orange vest or jacket that he found in the Microsoft truck. I was not able to see his face during the incident due to it being dark. He damaged several vehicles. Including the two Microsoft vehicles, a white vehicle belonging to David Tommasini from INAP, a black newer model sedan, a red smaller hatchback, and a tan van belonging to Security Officer Stahley. The vehicle belonging to David Tommasini had damage to the front end, Passanger side window, and back lights. The Microsoft vehicles were gone through and items were taken out of them. No obvious damage to the vehicles. No damage was reported from the other vehicles involved to SDC Security or staff. Below is a time line of the incident.

At about 2030 Subject is seen coming on property through IGE II building A. He walkes to the south parking area. 2036 Walks by stairs heading towards the Microsoft Truck.

2044 to 2104 Seen at the Microsoft Truck. He enters the vehicle and eventually comes out the passanger side.

2106 Puts on the orange vest or jacket that he found in the Microsoft truck.

2110-2158 Moves to the black newer model sedan. Looking around and under the vehicle. Pulling on the hood and door. He spends several minutes under the vehicle.

2158-2159 Looking at the Gray Van belonging to the Security Officer Stahly. Tugs at the hood.

2159-2203 Goes back to the Microsoft Truck and looks around it.

2203-2206 Goes to the white car belonging to David Tommasini. Looking in the windows.

2206-2208 A truck is seen at the top of the parking lot on the other side of the Ballards. Subject hurries over to the wooded area by the retaining pond until that vehicle leaves.

2208-2216 Subject goes to the small red hatchback and looks in the vehicle.

2216-2234 Subject goes back to the black car and hides around it as Mobile Patrol is in the area. When Mobile Patrol is in the upper parking area the subject darts around the black vehicle to hide from the view of Mobile Patrol.

2234-2239 Subject moves to the Gray Van and tugs at the hood of the vehicle.

2239-2250 Subject moves back to the black car. Looking around the vehicle.

2250-2328 Subject goes into the Microsoft Van. He enters first through the drivers side door. A person is seen arriving at about 2255 going down the stairs. The mobile patrol does a patrol in the area as the subject is in the Van. 2214 the red car leave site. Subject is seen going into the back of the Microsoft Van during this time. At 2324 he is seen taking a long silver pole out of the back of the Microsoft Van.

2328-2350 Seen walking between the white car and the Microsoft Truck. Collecting items that he took out of the Microsoft Vehicles in the

back of the Microsoft truck. Using the pole on the front end of the white car to possibly pop the hood. Eventually throwing the pole in the bushes next to the white car.

2350-0021 At the white car on the passanger side. Looking as if he is messing with the drivers window or side mirror. Attempting to pull at it. Works his way towards the back of the vehicle. Seen messing with the rear light until the alarm goes off at 0020. He walks away from the car.

0023-0034 Brings over bucket and bag to the front of the white car. Messing with the front end of the vehicle.

0034 Goes back into the Microsoft truck as Mobile Patrol arrives for a patrol

0040 Mobile Patrol Officer Singh finds the bucket and backpack from Mircosoft on the ground in front of the white vehicle. Subject can be seen hiding behind the Microsoft Van while Officer Singh takes the items to the main security office. When Officer Singh goes down the stairs the subject looks to where the items were at and walks off property going up the hill past the ballards at 0044. Officer Singh notices him and watches as he leaves property.

Capt Andrew Hair Signature:	Date: 2/23/2021 Time: 1026
-----------------------------	-----------------------------



Date of Incident: 2/24/2021

Time of Incident: 2245-2310

1. Client: Sabey Data Center		Address: 3355 S. 120 th Pl. Tukwila, WA			Post:SDC building 5
2. Client Notified: Yes		Time :0600	Name: Ryan Monson		Title: Operations Manager
Fire 3.G4S Notified: Yes		Time: 0600	Name: Joseph Beaux, Ed		Title: Operations Manager
File 5.645 Nouneu: 1 es				Christopher Neil	The operations Manager
4. Police Notified:		Time:	Officers Na	ame:	RPT#/Badge#:
5. Persons Involved/Witr	nesses (Insert categor	y of relationship l	etter opposit	e name in * column. A	. Employee B. Client Employee C.
Other)					
*	Name/Position Title	Pł	none #	Organ	ization Name & Address
А					
В					
C.					

6. Description of Property/Equipment. Fire alarm sounded with strobes going off, Trouble alarm in CP 3 Z28 first floor

7. Description of incident:


At about 2245 till about 2310 we had an incident in the Upper South Parking of fuel being stolen out of the Microsoft truck. This is an overview based on what was seen on the footage as well as the information provided by the Mobile Security Officer Peneueta. At about 2237 two vehicles can be seen coming onto property. One white van (see attached pictures) and one Ford diesel truck. At few minutes later the vehicles go up into the Upper South Parking. The white goes and backs into the parking spot next to the Mircosoft truck. The Ford truck goes and backs into a spot on west side of the parking lot next to the retaining pond.


You can see a subject coming out of the van and start to pull on the gas cap of the Microsoft truck. When he is unable to get into the gas cap you can see the subject pulling something out of the side door of the van. He lays under the Microsoft Truck. (later found out from Microsoft that he drilled holes in the gas tank and drained it)

At about 2302 Sabey Mobile Patrol Officer Peneueta is seen arriving and doing a patrol of the parking area. He notices the two vehicles. He stops at the van at about 2304 to make contact parking the patrol car in front of the van. The subject is seen trying to hide around his van while Officer Peneueta attempts to make contact. Officer Peneueta makes contact with the subject at the front of the vehicle. Officer Peneueta gets back into his vehicle and contacts Microsoft Security.

At about 2307 the Ford truck comes back and intimidates Mobile Officer Peneueta to get his vehicle out of the way so the van can leave as well. The truck is seen inching towards the patrol car in an attempt to make him back off. Officer Peneueta backs up and lets the vehicles leave without further incident. (see incident report from Officer Peneueta). The two vehicles leave via 124th.

	Capt A. Hair	Signature:	Date: 2.25.2021 Time: 0745
--	--------------	------------	------------------------------







Date of Incident: 04/12/2021

Time of Incident: 0230

1 01 4 0 1									
1. Client: Sabey Data Center		Address: 3355 S. 120 th Pl. Tukwila, WA			Post: N Lobby				
2. Client Notified: Yes		Time:0930		Name: Ryan Abel/Ryan		Title: Facility Engineer			
		N		Monson					
3.G4S Notified:	Yes	Time: 0700)	Name: Andrew Hair		Title: Security Supervisor			
4. Police Notifie	ed: No	Time: Officers Name:		ame:	RPT#/Badge#:				
5. Persons Invo	lved/Witnesses (Insert catego	ry of relation	nship le	tter opposite	e name in * column. A	. Employee B. Client Employee C.			
Other)		·	•						
*	Name/Position Title Phone # Organization Name & Address								
А	Greg Wren 2067956895					Consulting (Microsoft)			
В									
C.	C.								
6. Description of Property/Equipment. Greg Wren personal vehicle.									
7. Description of incident. On 4/12/2021 at about 0213 I can see via the reviewed camera footage that a black truck comes into the Upper South Parking and parks next to Greg personal vehicle. We can see someone come out of the truck and look around Greg's vehicle. The subject is wearing a hoodie and jeans. He can be seen going under the vehicle a couple times. The truck leaves at about 0231. Seen on Camera leaving via 124 th at about 0232. Greg Wren notified us at about 0700 that he had damage around his tail pipe. Like someone was trying to get to a converter.									
Our night officer notified mobile patrol at 0227 of a suspicious vehicle. At about 0235 Mobile Patrol investigates the vehicle and the other vehicles in the Upper South Parking lot. Sgt Rita does not go under the vehicle to check for damage. He looks at the windows, door, and steering columns. Not finding any damage Sgt Rita leaves about 10 min later.									



Date of Incident: 10/7/2020

Time of Incident: 2300-0700

1. Client: Sabey Data Center		Address: 3355 S. 120th Pl. Tukwila, W		cwila, WA	Post: N Lobby
2. Client Notified: Yes		Time :0800 Name :		n Able	Title: Assistant Manager
3.G4S Notified: N/A		Time: Name:			Title:
4. Police Notified: N/A		Time:	Officers Name:		RPT#/Badge#:
5. Persons Inv	volved/Witnesses (Insert catego	ry of relationship l	etter opposite	name in * column. A	. Employee B. Client Employee C.
Other)					
*	Name/Position Title		Phone # Organiza		ization Name & Address
А	Gregory Wren				TCS Microsoft
В					
C.					
(D ! !!	· C D · · · · · · · · · · · · · · · · ·				

6. Description of Property/Equipment.

7. Description of incident.

Between 10.6.2020 2300 to 10.7.2020 0700. Gregory Wren of TCS Microsoft vehicle was broken into at the upper south parking. In the diagonal parking between SDC building 5 and IGE II. The driver back window was smashed in. Gregory stated that he was last at his vehicle at about 2300 last night. He had several things stolen out of his vehicle. Two umpire bags with about \$400 dollars in gear. Owners manual for his vehicle, Various CD's, a new seat cover, and some cloths. He is going to file a police report.

END OF REPORT

Sec Capt Hair

Signature:

Date: | Time: 10.7.2020 0800



Security Unit Reporting: Mobile Patrol

Client: Sabey Date: 25 May 2021 Address: IGE Time: 01:40 AM

The following condition was noted and is brought to your attention for information or corrective action, as appropriate:

At approx. 01:40 AM I received a call from the Security Officer at SDC5 informing me of potential car prowlers in the upper parking lot while en route to IGE for routine patrol. The S/O updated me on the vehicle's location as I was driving. The vehicle left the parking lot at approx. 01:42 AM on S 124th and turned right (southbound) onto E Marginal Way. I saw this vehicle leave our property. I did not see a front license plate, so I turned around into IGE II to get a view of the back of the vehicle. The driver then took off at a high rate of speed and I was unable to see the rear license plate.

After the driver had left the vicinity, I inspected the vehicles in the upper parking lot and did not notice any obvious signs of theft or damage. I reviewed the footage of the vehicles path through IGE and from the Meraki recordings determined the vehicle entered IGE at approx. 01:36 AM from S 120th street, proceeded through IGE, entered the upper parking lot, peered into vehicles and left the property at approx. 01:42 AM. I asked the SDC5 S/O to review footage on the cameras I do not have access to.

While inspecting vehicles near BLDG 1, I noticed an open trunk on a vehicle in front of the N entrance to Sahale Snacks. With the assistance of another employee, I was able to locate the vehicles owner who informed me nothing was taken or damaged. After reviewing the security footage, it does not appear the vehicle had stopped near BLDG 1. I did not notice any signs of damage or theft on any vehicle at IGE or IGE II and did not see any security footage showing the vehicle travel through IGE II. The police were not contacted as the vehicle was leaving and no signs of theft or damage were seen. End of Report.

Reported by Sean Rita, SGT, Sabey Mobile Patrol

DO <u>NOT</u> WRITE BELOW THIS LINESECURITY OFFICER INSTRUCTIONS: Use this form to inform the Client and Branch Management of maintenance conditions that may warrant attention but that do not meet Incident Report criteria. This form should be used to report a problem or condition such as a loose door knob, a broken chair, a stiff lock, etc.

"Address" should be the client site or facility. "Time" entries should reflect the 24-hour clock (1310, 1630, 2210, etc.) "Location" should reflect the area within the Site or facility Items reported should be noted in the Daily Activity Report



Security Unit Reporting: Mobile Patrol

Client: Sabey

Address: IGE

Date: 25 May 2021

Time: 21:20hrs

The following condition was noted and is brought to your attention for information or corrective action, as appropriate:

At approx. 21:20hrs I was parked near BLDG 4 at IGE observing the property and watching the Meraki Security cameras when a blue Dodge Challenger entered the property and traveled westbound between BLDG's 2 & 3, towards Providence. I observed the vehicle turn to the rear parking lot behind BLDG 5 and the vehicle began burning out and doing donuts. I immediately informed SDC5 over radio and began traveling to intercept the vehicle. I made contact with the driver shorty after who made a joke about buying the vehicle. I informed him that this was private property, it was extremely dangerous to do stunts like that with people walking and driving around our property and that he is not allowed back on our property.

I radioed SDC5 the license plate of the vehicle, but I believe the radio cut out, so I am unsure if the full plate was recorded. I was not able to write down the plate as my full attention was on maintaining a safe distance from the vehicle. I followed the vehicle out of our property, they entered and exited on S 120th Street. End of Report.

Reported by Sean Rita, SGT, Sabey Mobile Patrol

DO <u>NOT</u> WRITE BELOW THIS LINESECURITY OFFICER INSTRUCTIONS: Use this form to inform the Client and Branch Management of maintenance conditions that may warrant attention but that do not meet Incident Report criteria. This form should be used to report a problem or condition such as a loose door knob, a broken chair, a stiff lock, etc.

"Address" should be the client site or facility.

[&]quot;Time" entries should reflect the 24-hour clock (1310, 1630, 2210, etc.)

[&]quot;Location" should reflect the area within the Site or facility Items reported should be noted in the Daily Activity Report



Security Unit Reporting: Mobile Patrol

Client: Sabey Address: IGE II

Date: Aug. 29, 2020 Time: 18:42

The following condition was noted and is brought to your attention for information or corrective action, as appropriate:

On Aug. 29,2020 at 18:42 I noticed the black gate between DHS public parking and IGE is damaged. I manually opened the other gate so no more damage would happen. I called the 24 on call engineer line and informed them of the problem. The on call engineer called back and I informed him of the problem. He said he would investigate the problem. No other issues to report.

In the past this same set of lights have been out due to a timer issue FYI.

Reported by: S/O Stahly, Sabey Mobile Patrol

DO <u>NOT</u> WRITE BELOW THIS LINESECURITY OFFICER INSTRUCTIONS: Use this form to inform the Client and Branch Management of maintenance conditions that may warrant attention but that do not meet Incident Report criteria. This form should be used to report a problem or condition such as a loose door knob, a broken chair, a stiff lock, etc.

"Address" should be the client site or facility.

"Time" entries should reflect the 24-hour clock (1310, 1630, 2210, etc.)

"Location" should reflect the area within the Site or facility Items reported should be noted in the Daily Activity Report



Security Unit Reporting: Mobile Patrol

Client: Sabey Address: IGE

Date: 7 Oct. 2020 Time: 18:00hrs

The following condition was noted and is brought to your attention for information or corrective action, as appropriate:

I was pulled aside by the neighbors that live close to the SE parking lot of IGE BLDG 5, and they proceeded to tell me that their house was robbed and the wooden blockade located in the parking lot was vandalized and pulled out of the ground. The wooden blockades are loose and the bolts holding it down, have been broken off. The neighbors have asked that Sabey please increase lighting in the area to increase deterrence. The on call engineer was not called at this was not an immediate emergency.

Reported by: Samson Peneueta, S/O, Sabey Mobile Patrol

DO <u>NOT</u> WRITE BELOW THIS LINESECURITY OFFICER INSTRUCTIONS: Use this form to inform the Client and Branch Management of maintenance conditions that may warrant attention but that do not meet Incident Report criteria. This form should be used to report a problem or condition such as a loose door knob, a broken chair, a stiff lock, etc.

"Address" should be the client site or facility.

"Time" entries should reflect the 24-hour clock (1310, 1630, 2210, etc.)

"Location" should reflect the area within the Site or facility Items reported should be noted in the Daily Activity Report



Security Unit Reporting: Mobile Patrol

Client: Sabey Date: 26 NOV 2020 Address: DHS Time: 11:05 PM

The following condition was noted and is brought to your attention for information or corrective action, as appropriate:

On 26 November 2020 at approx. 11:30 PM, I was driving back to DHS from IGE/IGE II and I discovered that the new line wire barrier had been cut. I investigated further and noticed that the black gate at DHS (top of hill) had also had its chain cut. I quickly checked for any persons/vehicles near the property. I also checked for any break ins/ missing items from DHS. Nothing had been taken or broken into. The gate just off property, (other side of 120th) Seattle Metro? There gate chain was also broken.

Reported by: S/O Singh, Sabey Mobile Patrol

DO <u>NOT</u> WRITE BELOW THIS LINESECURITY OFFICER INSTRUCTIONS: Use this form to inform the Client and Branch Management of maintenance conditions that may warrant attention but that do not meet Incident Report criteria. This form should be used to report a problem or condition such as a loose door knob, a broken chair, a stiff lock, etc.

"Address" should be the client site or facility.

- "Time" entries should reflect the 24-hour clock (1310, 1630, 2210, etc.)
- "Location" should reflect the area within the Site or facility Items reported should be noted in the Daily Activity Report



Security Unit Reporting: Mobile Patrol

Client: Sabey

Address: DHS

Date: 17 March 2021

Time: 1955 hrs

The following condition was noted and is brought to your attention for information or corrective action, as appropriate:

Arrived on site and found glass around the Kemp West trucks parked on the S end of the lowered parking lots. The glass was from a Kemp West truck and the Tenant had already placed cardboard over the window. No other damage or any signs of illegal activities found on said truck as well as the surrounding vehicles. Pics in phone.

Reported by S/O Peneueta Sabey Mobile Patrol

DO <u>NOT</u> WRITE BELOW THIS LINESECURITY OFFICER INSTRUCTIONS: Use this form to inform the Client and Branch Management of maintenance conditions that may warrant attention but that do not meet Incident Report criteria. This form should be used to report a problem or condition such as a loose door knob, a broken chair, a stiff lock, etc.

"Address" should be the client site or facility.

- "Time" entries should reflect the 24-hour clock (1310, 1630, 2210, etc.)
- "Location" should reflect the area within the Site or facility Items reported should be noted in the Daily Activity Report



Security Unit Reporting: Mobile Patrol

Client: Sabey Date: 27 July 2021 Address: IGE Time: 01:40 AM

The following condition was noted and is brought to your attention for information or corrective action, as appropriate:

I arrived on site at approx. 0200hrs when I discovered a suspicious truck parked next to the exterior generators outside of IGE bldg.2. He immediately speeds off the premises as soon as they see's the security vehicle. The vehicle was a dark blue Chevy pick up truck with tinted windows and landscaping tools in the flatbed. I successfully made sure the vehicle left the property and did not enter any other Sabey properties. I was not able to identify the vehicles license plates, as I was not able to get close enough to the car.

After patrolling the immediate area as well as IGE II to search for any signs of illegal activity, I discovered nothing. I also inspected the exterior generators and surrounding area to find no signs of illegal activity or property damages. I reported the incident to the Tukwila non emergency line and asked for a unit to patrol through the area, on top of trespassing the vehicle. I did not receive a call back. Prolonged patrols were conducted throughout the remainder of the shift.

End of Report

Reported by SGT Peneueta, Sabey Mobile Patrol

DO <u>NOT</u> WRITE BELOW THIS LINESECURITY OFFICER INSTRUCTIONS: Use this form to inform the Client and Branch Management of maintenance conditions that may warrant attention but that do not meet Incident Report criteria. This form should be used to report a problem or condition such as a loose door knob, a broken chair, a stiff lock, etc.

"Location" should reflect the area within the Site or facility Items reported should be noted in the Daily Activity Report

[&]quot;Address" should be the client site or facility.

[&]quot;Time" entries should reflect the 24-hour clock (1310, 1630, 2210, etc.)